

	Type	Hits	Search Text	DBs
1	BRS	11	5,051,861	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
2	BRS	16	4,429,340	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
3	BRS	4	"0432054"	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
4	BRS	15	"432054"	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
5	BRS	11	"4445079"	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
6	BRS	3678	(trip or tripping) adj device	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
7	BRS	205	(trip or tripping) adj device and display	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
8	BRS	75	(trip or tripping) adj device and display same (switch switches)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
9	BRS	6	(trip or tripping) adj device and display same (switch switches) and LCD	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
10	BRS	630	361/93.1	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
11	BRS	266	361/93.2	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
12	BRS	90	circuit adj breaker and (switch switches) near (program programming)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
13	BRS	53	circuit adj breaker and (switch switches) near (program programming) and display	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
14	BRS	21	circuit adj breaker and (switch switches) near (program programming) and display and front adj panel	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
15	BRS	167	circuit adj breaker same programming	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
16	BRS	21	circuit adj breaker same programming and front adj panel	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB

	Time Stamp	Comments	Error Definition	Errors
1	2003/12/29 14:31			0
2	2003/12/22 16:10			0
3	2003/12/22 16:11			0
4	2003/12/22 16:12			0
5	2003/12/22 16:24			0
6	2003/12/22 16:27			0
7	2003/12/22 16:27			0
8	2003/12/22 16:28			0
9	2003/12/22 16:32			0
10	2003/12/22 16:33			0
11	2003/12/23 09:06			0
12	2003/12/23 09:27			0
13	2003/12/23 10:19			0
14	2003/12/23 11:16			0
15	2003/12/23 11:16			0
16	2003/12/23 11:17			0

	Type	Hits	Search Text	DBs
17	BRS	20	circuit adj breaker same programming and front adj panel and switches	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
18	BRS	0	circuit adj breaker same programming and front adj panel and switches and displ	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
19	BRS	12	circuit adj breaker same programming and front adj panel and switches and display	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
20	BRS	5	("3529292"   "4556882"   "4754162"   "4977513"   "5051861").PN.	USPAT
21	BRS	12	circuit adj breaker and trip same programming and front adj panel and switches and display	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
22	BRS	13	("3941989"   "4331997"   "4351013"   "4409665"   "4653073"   "4685024"   "4752853"   "4825143"   "4827369"   "4866557"   "4983955"   "5007013"   "5224011").PN.	USPAT
23	BRS	13	("3941989"   "4331997"   "4351013"   "4409665"   "4653073"   "4685024"   "4752853"   "4825143"   "4827369"   "4866557"   "4983955"   "5007013"   "5224011").PN.	USPAT
24	BRS	3	5,852,643	USPAT
25	BRS	5	5,825,643	USPAT
26	BRS	24	5,038,246	USPAT
27	BRS	60	361/93.3	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
28	BRS	1024	lcd and no adj power	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
29	BRS	456	lcd adj display and no adj power	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
30	BRS	12	lcd adj display and no adj power and kent	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB

	Time Stamp	Comments	Error Definition	Errors
17	2003/12/23 11:17			0
18	2003/12/23 11:17			0
19	2003/12/23 13:32			0
20	2003/12/23 11:32			0
21	2003/12/23 14:58			0
22	2003/12/23 13:55			0
23	2003/12/23 15:30			0
24	2003/12/23 15:31			0
25	2003/12/23 15:31			0
26	2003/12/23 16:27			0
27	2003/12/23 16:28			0
28	2003/12/29 11:15			0
29	2003/12/29 11:15			0
30	2003/12/29 11:51			0

	Type	Hits	Search Text	DBs
31	BRS	58	( "4002886"   "4291304"   "4500880"   "4766295"   "4870398"   "4901066"   "4908613"   "4916441"   "4948232"   "5019811"   "5111196"   "5172314"   "5216233"   "5241467"   "5245534"   "5250789"   "5251048"   "5295064"   "5296953"   "5298476"   "5313569"   "5374815"   "5380991"   "5448046"   "5448226"   "5457307"   "5461561"   "5465085"   "5473146"   "5506600"   "5532465"   "5570216"   "5583487"   "5587264"   "5645758"   "5704049"   "5729695"   "5729696"   "5736967"   "5751257"   "5758064"   "5771005"   "5794211"   "5794215"   "5797132"   "5812985"   "5839116"   "5870714"   "5918212"   "5926797"   "5929770"   "5987426"   "5988498"   "5999913"   "6009538"   "6012040"   "6016481"   "6026373" ) .PN.	USPAT
32	BRS	7	( "3959902"   "3963326"   "4074253"   "4800381"   "4864752"   "6034807"   "6088013" ) .PN.	USPAT
33	BRS	34	5,224,011	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
34	BRS	122	361/93.4	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
35	BRS	62	361/93.5	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB

	Time Stamp	Comments	Error Definition	Errors
31	2003/12/29 11:26			0
32	2003/12/29 11:28			0
33	2003/12/29 14:12			0
34	2003/12/29 14:12			0
35	2003/12/29 14:32			0